

## **CLAMP-ON METERS**

500 Series








### Models 500, 502 & 503

**Small compact size** clamp-meter that fits comfortably in a tool bag











# **► SPECIFICATIONS**

MODELS	500	502 TRMS	503
<b>AC Current</b> (Auto-Ranging)	0.05 to 400A	0.05 to 400Arms	0.05 to 400A
Resolution	0.1A	0.01A and 0.1A	0.01A and 0.1A
Accuracy 50 to 60Hz 60 to 500Hz	±2% of Reading ± 5cts ±2.8% of Reading ± 5cts	±1.9% of Reading ± 5cts ±2.5% of Reading ± 5cts	$\pm 1.5\%$ of Reading $\pm 10$ cts $\pm 2.5\%$ of Reading $\pm 10$ cts
AC Voltage (Auto-Ranging)	0.5 to 600V	0.5 to 600Vrms	0.5 to 600V
Resolution	0.1V and 1V	0.1V and 1V	0.1V and 1V
Accuracy 50 to 60Hz 60 to 500Hz	±1.0% of Reading ± 5cts ±1.5% of Reading ± 5cts	$\pm 1.5\%$ of Reading $\pm$ 5cts $\pm 1.5\%$ of Reading $\pm$ 5cts	±0.8% of Reading ± 5cts ±1.5% of Reading ± 5cts
Input Impedance	1MΩ	1MΩ	10MΩ
<b>DC Current</b> (Auto-Ranging)	_	_	0.10 to 400A
Resolution	_	_	0.01A and 0.1A
Accuracy	_	_	±2.5% of Reading ± 10cts
DC Voltage (Auto-Ranging)	_	0.2 to 600V	0.2 to 600V
Resolution	_	0.1V and 1V	0.1V and 1V
Accuracy	_	±1% of Reading ± 2cts	±1% of Reading ± 2cts
Input Impedance	_	1MΩ	10MΩ
Resistance	$0.3$ to $400\Omega$	$0.2$ to $400\Omega$	$0.2$ to $400\Omega$
Accuracy	±1.9% of Reading ± 3cts	±1% of Reading ± 2cts	±1% of Reading ± 2cts
Max Test Voltage	-1.6VDC	1.5Vpc	1.5VDC
Continuity	<35Ω	<40Ω	<40Ω
Max Test Voltage	1.5Vpc	1.5Vpc	1.5VDC
Frequency (Auto-Ranging)			
CURRENT INPUT			
Range 20Hz to 4kHz	_	1Hz Resolution	_
>4kHz to 10kHz	_	10Hz Resolution	_
Accuracy	_	±0.1% of Reading ± 1ct	_
Min Input Signal	_	2Arms	_
Input Impedance	_	1ΜΩ	_
Overload Protection	_	600Arms	_
VOLTAGE INPUT			
Range 10Hz to 4kHz	_	1Hz Resolution	_
>4kHz to 40kHz	_	10Hz Resolution	_
>40kHz to 400kHz	_	100Hz Resolution	_
Accuracy	_	±0.1% of Reading ± 1ct	_
Min Input Signal 4kHz	_	5Vrms	_
40kHz	_	5Vrms	_
400kHz	_	5Vrms	_
Input Impedance	_	1ΜΩ	_
Overload Protection	_	600Vrms	_
Power Source	Tw	o 1.5V AAA batteries (includ	ed)









### **► FEATURES**

- · Compact size fits into your pocket
- 400Aac or 400Aac/dc current measurements
- 600Vac/dc volts measurements
- TRMS measurements (Model 502)
- Resistance measurements to  $400\Omega$
- · Continuity with beeper below 40Ω
- Frequency measurements from V and A (Model 502)
- · Hold function to "freeze" readings
- · Push-button for easy ADC zeroing (Model 503)
- · Large, easy-to-read 4000-count display
- 42-segment analog bargraph
- · Includes test leads and soft carrying pouch

#### ► PRODUCT INCLUDES

Soft carrying case, set of two test leads, two 1.5V AAA batteries and user manual.



CATALOG NO.	DESCRIPTION
2117.54	Clamp-On Meter Model 500 (AC, 400Aac, 600Vac, Ohms, Continuity)
2117.66	Clamp-On Meter Model 502 (TRMS, 400Aac, 600Vac/DC, Ohms, Continuity)
2117.22	Clamp-On Meter Model 503 (AC/DC, 400AAC/DC, 600VAC/DC, Ohms, Continuity)